



SYMBOL DEFINITION			MISSING SYMBOLS	
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL ○ DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.			NO MISSING SYMBOL NUMBER	
TOTAL NO OF INSPECTIONS REQUIRED			9	
LAST NO. USED			9	

DATE		STG	REV	N/P	CHG	ZONE	REVISION HISTORY		AUTH	DR	AP/D	AP/D
18JA01	R	01	-	-	-	-	ALL PARTS - REDRAWN TO PD		205857	EOV	EOV	JA
10MY02	R	02	-	-	-	-	ALL PARTS - REVISED DRAFT ON FRONT LOCK AREA		225251	EOV	EOV	RC
11DE02	R	03	-	-	-	-	ALL PARTS - 20.7 +0.3/-0.15 WAS 20.7 +0.2/-0.15		234561	EOV	EOV	RC
21AU03	R	04	-	-	-	-	ALL PARTS - REVISED CAVITY TO MATCH ESD & REVISED DRAFT ON FRONT LOCK AREA		244745	EOV	EOV	AM
01JL04	R	05	-	-	-	-	ALL PARTS - REMOVED TWO OPTIONAL CONSTRUCTION VIEWS; ADDED DIM TO TGD		256451	JS	JS	TM
12AP06	R	06	-	-	-	-	ALL PARTS - UPDATED PDM ATTRIBUTES		276333	JS	JS	TM
27DE06	R	07	-	-	-	-	12146103 - OBSOLETE		288195	MDH	FRG	GG
26JA07	R	08	-	-	-	-	ALL ACTIVE PARTS - REMOVED NOTE 5		400344	HCB	JVM	WTM



VIEW SCALE DOES NOT REFLECT
ACTUAL PART SIZE

B PROCESS SENSITIVE DIMENSION										REFERENCE	
DIMENSIONS ENCLOSED IN  INDICATE REFERENCE DIMENSIONS AND 10 TOLERANCE LIMITS ARE ESTABLISHED											
DIMENSIONAL RANGE (MM)										THIRD ANGLE PROJECTION	
FROM TO										DO NOT SCALE	
TO > 0 > 20 > 30 > 70 > 100 > 150 > 200 > 250 > 300 > 400											
TOLERANCE UNLESS OTHERWISE SPECIFIED										USE MATH DATA	
10 15 20 2 20 3 30 4 40 5 50 6 60 8 8 1 2											